Health and Safety Solution

Workplace Health and Safety Queensland

Separating forklifts and workers

What is the problem?

Workers are at risk of being injured if workplaces do not take adequate measures to separate forklifts and pedestrians.

What are the risks?

Even at low speeds forklifts can cause serious injuries and fatalities. Not separating forklifts and pedestrians can result in injuries to forklift operators as well as to pedestrians, who can be crushed against a wall, object or another vehicle.

What is a solution to the problem?

Having an adequate traffic management system for managing forklift and pedestrian movements will reduce the risks of forklift related injury.

Options for physically separating forklifts and pedestrians include:

- Elevated walkways Where possible, pedestrians should be completely segregated from plant or vehicular traffic using elevated walkways.
- Barriers

Installing physical safety barriers and containment fences will separate pedestrians from forklifts and other mobile plant. This allows forklift operators to clearly see exclusion zones and pedestrian access points in the workplace.



Elevated walkway



Barrier system combined with a pedestrian crossing



- Dedicated waiting areas Where possible, workers should not access loading/receiving areas when forklifts are in operation. Creating dedicated waiting areas for truck drivers will help to prevent accidents between forklifts and pedestrians while unloading occurs.
- Pedestrian calming
 A process should be implemented to
 prevent workers from walking across
 designated forklifts areas. Using inward
 opening gates as part of a barrier system
 creates an understanding that workers
 need to stop and take notice of vehicle
 movements before crossing the
 designated traffic area.

Further information

For further information, call the Workplace Health and Safety Infoline on 1300 369 915 or visit <u>www.worksafe.qld.gov.au</u>

More information about forklift safety is available in *Forklift safety – reducing the risks*.

Images and some content reproduced with permission from Accident Research Centre – Monash University.



Loading/receiving area with truck drivers physically separated from forklifts



Barrier system in combination with pedestrian gates

© The State of Queensland (Department of Justice and Attorney-General) 2011

Copyright protects this document. The State of Queensland has no objection to this material being reproduced, but asserts its right to be recognised as author of the original material and the right to have the material unaltered.

The material presented in this publication is distributed by the Queensland Government as an information source only. The State of Queensland makes no statements, representations, or warranties about the accuracy or completeness of the information contained in this publication, and the reader should not rely on it. The Queensland Government disclaims all responsibility and all liability (including, without limitation, liability in negligence) for all expenses, losses, damages and costs you might incur as a result of the information being inaccurate or incomplete in any way, and for any reason.

Workplace Health and Safety Queensland, Department of Justice and Attorney-General Health and Safety Solution – Separation of forklifts and workers PN11083 Version 1 Last updated August 2011